


# (Z)WGT The Dalvey Grand Tourer Chronograph

## Adjusting the hands to zero position

Example: One or several chronograph hands are not in their correct zero positions and have to be adjusted (e.g. following a battery change).




### Starting calibration

To start calibration mode hold down **B** and press **A** till both hands start to move.

If both hands start to move when only **B** is pressed then you are already in calibration mode

(The second hand will turn 40° and the minute counter will turn 360°)




### Adjusting the minute counter hand

Single step ↙ **B** for one movement of the minute hand

Hold down ↙ **B** for continuous

(Note. the second hand will also move)

Move till minute hands is at the 12 o'clock position




### Adjusting the second hand

Single step ↙ **A** for one movement of the second hand

Hold down ↙ **A** for continuous

Move till second hand is at the 12 o'clock position



### Ending calibration

Push both **A** and **B** buttons for 2 seconds

(The second hand and the minute counter will turn 360°)

Termination of chronograph hands adjustment  
(can be carried out at any time)